



January 14-16, 2026
42nd CRCA Trade Show & Seminars

I Wouldn't Do That If I Was You...

Current Technical Roofing Issues From Field Forensics



Speaker:

Matt Dupuis PhD PE

SRI Consultants

Topics

- Cold Roof Designs
- Membrane Issues
 - EPDM
 - TPO
- Induction Welded Plates
- Latent Material Moisture
- Low Rise Adhesive Foams
- Fleece Backed Membranes
- Roof Drains


Introduction

- These are issues that are repetitive legal issues or unique (interesting) in low slope roofing.
- Even though specific products or manufacturers may be involved
 - Out of professional curtesy, no names will be used, no specific buildings or locations will be discussed.
 - If you know or think you know what is being discussed, please keep it to yourself (Professional Curtesy)
- This presentation is for avoidance of repeating these mistakes or issues by those here.


Cold Roof Designs

- This issue continues to be the most repetitive issue in legal and insurance cases
- Very expensive to correct and or remediate
- Almost always a design issue

Cold Roofs, What is it?



COLD ROOF




WARM ROOF

Cold Roofs, What is it?


- Roof design where all or most of the insulation is below the roof deck
 - This is what most steep slope roofs are for residential homes and vented
 - Here they are in a low slope configuration
- Typically, this design was used to meet an exemption in fire code for multifamily to avoid the use of sprinkler system in interstitial space
- R-40 to R-60 of insulation results in this space
 - Incredibly energy efficient!
 - Right?

Cold Roof Designs

- Problem is air leakage
 - Low voltage systems
 - Light fixtures
 - HVAC ductwork
 - Bathroom fans
 - Dryer vents
- All of these leak air to varying degrees
- Roof deck is almost same temperature as exterior
- Typical indoor air can have dew point temperatures in the 40-50°F range
- Deck condensates and moisture-based damage occurs





















Cold Roof Designs

- Even when everyone agreed what went wrong, roofer was drug along in legal proceedings
- There have been variations of this scenario
- 99.99% ultimately blamed on Designer of Record's choice for cold roof
- Fix?
 - Repair moisture damage
 - Place insulation above roof deck
 - Keep the roof deck warm and not a condensing surface
 - As little as R-5 to R-10 has been anecdotally shown to prevent the decay
 - Experience shows that code required insulation will protect the roof deck even without sealing and ducts or penetrations
- See *Professional Roofing – Know the Facts*, March 2022 for article

Cold Roof Designs

- Ultimate fix...Don't build them like that!
- Insulation above deck
- **Can I vent it?...Maybe.**
- General rule has been that low slope roof do not lend themselves well for passive venting.
 - Active venting has it own risks
 - Single case in Southern Wisconsin where owner opted to vent.
 - Somewhat unique case where the apartment is a perfect square with venting space (inadvertent) and in a very windy corridor adjacent to interstate.
 - Continuous vents cut into all parapets
 - But it appears to be working (moisture readings and data loggers)


Membrane Issues

- Self Adhering EPDM
 - Shrinkage
 - Believed to be mechanical not formulation
 - End lap slippage
 - Side lap wrinkles -> fish mouths
 - One product, one manufacturer



Membrane Issues

- SA EPDM
 - Corrective action from manufacturer has been to apply cover tape to all laps
 - Appears to be sufficient correction
 - This is typically done for extended warranties, and this tends to quell fears of owners
- TPO
 - Single interesting case
 - East coast contractor had project where the TPO was cratering at laps
 - Small pieces of membrane were “popping off” during welding
 - Remember this is 800-1000°F welding temperatures



DL2
L=30.973 mil

DL1
L=21.119 mil

DL0
L=54.093 mil

20.0 mil



DL0
L=31.867 mil

DL1
L=24.919 mil

DL2
L=55.256 mil

Membrane Issues

- TPO
 - Speculated to be too high moisture content in TPO ingredient
 - Magnesium hydroxide (fire retardant) was speculated to have been received and sent to line with high moisture
 - Hard to prove after the fact
 - Ultimate fix would have been full sheet replacement
 - Owner accepted a coating
- Moral is even with mature product line we can find material or production issues that slip out the door

Induction Welded Plates

- For decades induction welded membranes have been “relatively” trouble free and great performers
- Past several years problems popped up
- Two plates
 - Black = PVC membranes
 - Gold = TPO membranes
- Problem primarily has been with Black / PVC plates

Induction Welded Plates

- Welds made with experienced staff, calibrated weld machines
- Hours to days after install welds would just fail, leaving membrane loose
- Manufacturer technical staff would come to job site to calibrate and demonstrate “how to weld it right”
 - Their welds would fail too
- Issue appears to be a change in plate production
- Very recently TPO plates have reported to have this issue too

Induction Welded Plates

- Additionally, we have seen pictures of fractures in the metal of new plates at fastener opening.
 - Metallurgical or die issue?
- Variation seen in saturated roof systems where black coating on plates will detach from metal plate
 - Membrane left unattached



Induction Welded Plates

- Best advice
 - Photograph and save lot numbers on plate boxes
 - Save test welds for extended period
 - Inform field staff not to ignore issues and just “reweld” again and again

Latent Material Moisture

- Result of heavy vapor retarders combined with thick insulation and coverboard system
- Any free moisture in insulation and coverboard is now stuck between membrane and vapor retarder
- Physically a minor amount of moisture
- But enough to trigger moisture meters
- Open the roof to dry air and moisture leaves in minutes





Latent Material Moisture

- Store materials as close to manufacturers instructions as possible
- Understand that a moisture meter is not calibrated to that material (typically)
 - So, use as an indicator but don't believe the numbers
- Do not store materials over surfaces that can readily emit moisture
 - Grass, gravel, sand
 - Avoid poly tarps tight to ground (greenhouse)

Low Rise Foams

- Discussed at CRCA 2024
- As manufactured and mixed Part A + Part B 1:1 ratio all is well
 - Very strong bond
- Problem has been field mixing and application
 - Temperature
 - Equipment issues (off ratio)
 - Foam ribbon spacings









Low Rise Foams

- Problems
 - Off Ratio foam – equipment issue
 - Ribbon spacing – labor issue
 - Unreacted foam – mixing issue or materials
- Suggestions
 - Invest in foam carts with sensors for pressure (alarms)
 - We used kettles and one worker responsible for kettle, time for this again
 - Clean out old foam in warehouse
 - Asphalt used to be our magic sauce to make roofs work, foam is the secret sauce now, treat it as such.

Fleece Back Membranes

- Absolutely fascinating issue for roof nerds
- Fleece back membranes are typically polyester fleece
- Multiple roofs over light weight insulating concrete that was not vented correctly or at all in Gulf Coast region
 - Elevated moisture under membrane
 - Fleece back TPO
- 4-6 years of age

Fleece Back Membranes

- **Fleece was gone**
- Not damaged, not failing to adhere, not discolored...GONE
- One roof all fleece was gone. Bareback membrane remained
- One roof was spotty with areas that were fine others were bare
 - Varied with moisture
- Alkaline environments (high pH) attack polyester
 - Need the liquid moisture as electrolyte
 - Are there other chemicals at play from concrete?

Fleece Back Membranes

- Sampled Fleece Back PVC
 - Fresh concrete + distilled water
 - Wash water from concrete chute
 - Liquid Drano Max
- Three weeks at 120°F
- Fleece was just beginning to fall apart
 - Particles settling at bottom
 - Bits floating
- So, this reaction appears to takes time months/years not days

Drains

- Adjustable roof drains are not designed for static water pressure!
- **DO NOT** plug these drains
- Pressure will cause water to leak through threads and gaskets in drain assembly into roof
- Over time volume of water in the roof increases
- Roofer gets blamed for “leaking roof”
- When in fact the water is going through the drain assembly



Dome

3/8-16 x 1 1/4 Bolt and Washer (4 Req'd.)
(Use pipe sealer on threads)

Flashing Clamp



Adjustable Sleeve



0.295 Dia. O-Ring




3/8-16 x 1 3/4 Bolt (4 Req'd.)
3/8 White Teflon Washer (4 Req'd.)
Clamp Ring with O-Ring Groove



Flat Gasket



Body



Roof Sump Receiver Suffix -R
(Recommended Option)



Underdeck Clamp Suffix -C
(Recommended Option)

-EA (Option)



Drains

- Multiple cases where the drains were plugged intentionally or by debris (and the general contractor knew)
 - One case plumbing wasn't done, but they wanted the roof installed. So, they plugged primary and secondary drains. Up to 18 inches of water at drains for months
 - Another case debris from construction plugged 8 of 24 drains on roof. General Contractor knew about it for over a year
 - Rain would back up onto roof
 - 1-2 inches of water inside roof system
- Builders risk considered it an “occurrence” each time it rained and claimed the \$250,000 deductible applied each time it rained. So, they owed nothing for multimillion dollar losses of the roofs
- Multiple cases of this around the country

Questions?

Contact info

- Matt Dupuis, PhD PE
- SRI
- E-Mail : mdupuis@sri-engineering.com